

Counterfeit Intertek Certification Certificate / Certificat de certification Intertek de contrefaçon

ATM for Report 2310A0926SHA-001, Product Wall Charger / ATM pour le rapport 2310A0926SHA-001, Chargeur mural de produit

Notification Type:	Counterfeiting / Contrefaçon
Certification Type:	Not Intertek Certified

Notification

Intertek notifies consumers, retailers and distributors that we have been made aware of counterfeit Intertek certificates in the marketplace as identified below claiming products are Intertek Certified. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés de la contrefaçon de certificats Intertek sur le marché comme indiqué ci-dessous les produits de revendication sont certifiés Intertek.

Company Identification

Unknown

Product Identification

This counterfeit notice affects ATM dated November 29th, 2023, for unknown company, certifying the product wall charger, model CD-005, FRW021, FRW336, SFT6677, SM6677, SFT6677-B, SM6677-B, DLP4314, DLP4314CD, FRW020-C, XHC8-1032-BLK, XHC8-1033, XHC8-1033-WHT, FRW225, FRW367, CX3097, TC010, MI TC010, MIC-TC010, HW-TC010, CTC-TC010, FRW057-V, FRW0097, TC010, MI-TC010, MIC-TC010, HW-TC010, CTC-TC010, FRW708-C, FRW947, SM6755-B, SM6755, CD-0067, FRW031A, FRW031B, FRW032B, XHC8-1032-BLK, XHC8-1032, XHC8-1032-WHT, FRW033B, FRW033W, FRW035A, FRW036A, FRW037A, FRW038A, SM6755-B, SM6755, TC014, MI-TC014-101, MI-TC014-100, MITC014-652, MI-TC014-XXX, BY-PD-W3-104-WT, BY-PD-W3-104-XX, BY-PD-XX-XX-XX, BY-PD-W3-204WT, BY PD-W3-204-AC, control number 5024921. Photos are on Page 2.

Cet avis de contrefaçon concerne ATM daté du 29 novembre 2023, pour une entreprise inconnue, certifiant le produit chargeur mural, modèle CD-005, FRW021, FRW336, SFT6677, SM6677, SFT6677-B, SM6677-B, DLP4314, DLP4314CD, FRW020-C, XHC8-1032-BLK, XHC8-1033, XHC8-1033-WHT, FRW225, FRW367, CX3097, TC01097 0, MITC010, MIC-TC010, HW-TC010, CTC-TC010, FRW057-V, FRW0097, TC010, MI-TC010, MIC-TC010, HW-TC010, CTC-TC010, FRW708-C, FRW947, SM6755-B, SM6755, CD-0067, FRW031A, FRW031B, FRW032B, XHC8-1032-BLK, XHC8-1032, XHC8-1032-WHT, FRW033B, FRW033W, FRW035A, FRW036A, FRW037A, FRW038A, SM6755-B, SM6755, TC014, MI-TC014-101, MI-TC014-100, MITC014-652, MI-TC014-XXX, BY--W3-104-WT, BY--W3-104-XX, BY--XX-XX-XX, BY--W3-204WT, BYPD-W3-204-AC, numéro de contrôle 5024921. Les photos se trouvent à la page 2.

Hazard Involved

Not Intertek Certified / Non certifié Intertek

What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published: August 29, 2024
Revised:

Public Notice ID: 2024-50
Page 2 of 2

Photos and Images / Photos et images

COUNTERFEIT



AUTHORIZATION TO MARK

This authorizes the application of the Certification Mark(s) shown below to the models described in the Product(s) Covered section when made in accordance with the conditions set forth in the Certification Agreement and Listing Report. This authorization also applies to multiple Issue model(s) identified on the correlation page of the Listing Report.

This document is the property of Intertek Testing Services and is not transferable. The certification mark(s) may be applied only at the location of the Party Authorized To Apply Mark.

Applicant: _____ Manufacturer: _____

Address: _____ Address: _____

Country: CHINA Country: CHINA

Party Authorized To Apply Mark: Same as Manufacturer
Report Issuing Office: Intertek Testing Services Shanghai Limited

Control Number: 5024921 Authorized by: [Signature]
Mr. L. Matthew Snyder, Certification Manager



This document supersedes all previous Authorizations to Mark for the noted Report Number.

This Authorization to Mark is the result of an agreement between Intertek and the Client in accordance with the Certification Agreement. Intertek and the Client are not responsible for any damage or loss resulting from the use of this Authorization to Mark. The Client is authorized to apply the ETL mark to the product(s) listed in the Listing Report. The Client is responsible for ensuring that the product(s) listed in the Listing Report are made in accordance with the conditions set out in the agreement and in the Listing Report. The Client is responsible for ensuring that the product(s) listed in the Listing Report are made in accordance with the conditions set out in the agreement and in the Listing Report. The Client is responsible for ensuring that the product(s) listed in the Listing Report are made in accordance with the conditions set out in the agreement and in the Listing Report.

Intertek Testing Services NA Inc.
545 East Algonquin Road, Arlington Heights, IL 60005
Telephone 800-345-3851 or 847-439-5667 Fax 312-265-1672

Standard(s):	Audio/Video, Information and Communication Technology Equipment - Part 1: Safety Requirements [UL 62388-1:2019 Ed.3+R:22Oct2021]
Product:	Audio/Video, Information and Communication Technology Equipment - Part 1: Safety Requirements [CSA C22.2 No. 238-1:2019 Ed.3+U1]
Models:	Wall charger CD-005, FRW021, FRW336, SFT6677, SM6677, SFT6677-B, SM6677-B, DLP4314, DLP4314CD, FRW020-C, XHCS-1032-BLK, XHCS-1033, XHCS-1033-WHT, FRW225, FRW367, CX3097, TC010, MI-TC010, MIC-TC010, HW-TC010, CTC-TC010, FRW067, FRW067, TC010, MI-TC010, MIC-TC010, HW-TC010, CTC-TC010, FRW708-C, FRW947, SM6755-B, SM6755, CD-0067, FRW031A, FRW031B, FRW032B, XHCS-1032-BLK, XHCS-1032, XHCS-1032-WHT, FRW033B, FRW033W, FRW035A, FRW035A, FRW037A, FRW038A, SM6755-B, SM6755, TC014, MI-TC014-101, MI-TC014-100, MITC014-352, MI-TC014-XXX, BY-PD-W3-104-WT, BY-PD-W3-104-XX, BY-PD-XX-XX-XX, BY-PD-W3-204WT, BY-PD-W3-204-AC.