

ISP OR ORGANIZATION	VERIFIED SERVICES
911 Safety Equipment LLC 9 S Forrest Ave. Norristown, PA 19401 Valid Through: 3/18/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast 488-200 Repair Tape
Advanced Emergency Services Training Services Inc. dba AEST Fire & Safety 304 N Wilkinson Dr. Laurinburg, NC 28352 Valid Through: 7/19/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Advanced Fire Gear Repair 1902 Campus Place, Suite 3 Louisville, KY 40299 Valid Through: 10/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
Choice Clean Gear LLC 200 Turner Industrial Way Aston, PA 19014 Valid Through: 04/11/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Curtis PPE 517 W. Sunset Road Henderson, NV 89011 Valid Through: 04/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Parallon Type B2 Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Curtis PPE 1635 Gramercy Road Salt Lake City, UT 84104 Valid Through: 05/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Black Crosstech 3-layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Curtis PPE 6723 Sierra Ct Suite D Dublin, CA 94568 Valid Through: 04/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
Curtis PPE 15523 Carmenita Road Santa Fe Springs, CA 90670 Valid Through: 05/15/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com

ETL NFPA 1851-2020 VERIFIED ISP's AND ORGANIZATIONS

ISP OR ORGANIZATION	VERIFIED SERVICES
Curtis PPE 4647 S. 33rd Street Phoenix, AZ 85042 Valid Through: 04/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Curtis PPE 6507 S. 208th Street Kent, WA 98032 Valid Through: 04/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Delta Fire & Safety Inc. dba Delta Industrial Service & Supply 3159 Summit Drive Port Neches, TX 77651 Valid Through: 05/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
D&D Mountain Air Cleaners dba Southwest PPE Services 309 S Paseo De Onate Espanola, NM 87532 Valid Through: 06/13/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
FireClean, Inc. 533 NE 34th Court Oakland Park, FL 33334 Valid Through: 10/03/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
Fire Safety Services, Inc. 6228 Road 95 Huntsville, OH 43324 Valid Through: 09/24/2023	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Valid Through: 05/30/2027 3415 Bryn Mawr Dr. NE Albuquerque, NM 87107 Valid Through: 10/30/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Florida PPE Services, Inc. 970 Sunshine Lane, Units J/K Altamonte Springs, FL 32714 Valid Through: 07/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com	

ISP OR ORGANIZATION	VERIFIED SERVICES
Fort Worth Fire Department 2900 W Bolt Fort Worth, TX 76110 Valid Through: 09/05/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Fire-Dex, GW LLC 9030 Viscount Row Dallas, TX 75247 Valid Through: 10/14/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Parallon Type B2 Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1202 & TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1202 & TX1912-NA-B Repair Tape
Fire-Dex, GW LLC 3660 Thousand Oaks Dr., Ste 112 San Antonio, TX 78247 Valid Through: 10/16/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •W.L. Gore Parallon Type B2 Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1202 & TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1202 & TX1912-NA-B Repair Tape
Hawaii PPE 94-155 Leo'ole St., Suite D406 Waipahu, HI 96797 Valid Through: 05/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
LFUCG, Div. of Fire & Emergency Services Lexington Fire Department 219 East Third St. Lexington, KY 40508 Valid Through: 07/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape
Maryland Fire Equipment Corp. 12284 Wilkins Ave. Rockville, MD 20852 Valid Through: 07/31/2025 Valid Through: 05/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape
Norcal PPE 4505 Golden Foothills Parkway, Suite 1 El Dorado Hill, CA 95762 Valid Through: 12/30/2026	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1902 Repair Tape
RDF Inc., dba Paul Davis 3641 South 6th St. Lincoln, NE 68502 Valid Through: 12/13/2025	Advanced Cleaning & Sanitization Verified Cleaner
Safe Industries 5031 Hwy 153 Easley, SC 29642 Valid Through: 2/17/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore Crosstech 3 Layer Type 4A Moisture Barrier w/ W.L. Gore 6GTAM038WHTJ Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape

This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com

ISP OR ORGANIZATION	VERIFIED SERVICES
Scott's PPE Recon 827 Black Diamond Way, Bldg. C Lodi, CA 95240 Valid Through: 3/31/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
SoCal PPE, LLC 2146 Main Street San Diego, CA 92113 Valid Through: 02/27/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Solutions of New Orleans LLC 4929 E Judge Perez Dr. Violet, LA 70092 Valid Through: 07/31/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair Gold Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Turnout Express LLC 1250 Scottsville Road, Suite 90 Rochester, NY 14624 Valid Through: 4/12/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Turnouts, LLC 5824 Akron Cleveland Road, Suite C Hudson, OH 44236 Valid Through: 02/05/2023	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Turnout Maintenance Co., LLC 7734 Garden Grove Blvd. Westminster, CA 92683 Valid Through: 02/28/2026 Valid Through: 05/30/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
United Safety Group 4110 Butler Pike, Suite A-103 Plymouth Meeting, PA 19462 Valid Through: 12/13/2025	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
Vogelpohl Fire Equipment, Inc. 2770 Circleport Drive Erlanger, KY 41018 Valid Through: 03/18/2027	Advanced Cleaning & Sanitization Advanced Inspection Advanced Repair of: •Outer Shell •Thermal Liner •W.L. Gore Black Crosstech Type 2F Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •W.L. Gore RT7100 Type 3D Moisture Barrier w/ W.L. Gore 10880780/10880782 Repair Tape •Stedfast Stedair 3000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape •Stedfast Stedair 4000 Moisture Barrier w/ Stedfast Air 3000 TX1912-NA-B Repair Tape
This document identifies ISP and organizations who have received ETL-Verification of Conformity to NFPA 1851 as of the revision date. Verification is valid only for the Repair Facility at the mailing address identified above. To confirm a Repair Facility holds a current ETL-Verification of Conformity, please contact Ann Overbaugh at ann.overbaugh@intertek.com	